



MISCELLANEOUS PAPER S-73-47

# CONDITION SURVEY, FT. DEVENS ARMY AIRFIELD, FT. DEVENS, MASSACHUSETTS

by

R. D. Jackson, P. J. Vedros

COPY AVAILABLE TO DDC DOES NOT PERMIT FULLY LEGIBLE PRODUCTION



June 1973

Sponsored by Office, Chief of Engineers, U. S. Army

Conducted by U. S. Army Engineer Waterways Experiment Station
Soils and Pavements Laboratory
Vicksburg, Mississippi

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

Destroy this report when no longer needed. Do not return it to the originator.

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.




9 MISCELLANEOUS PAPER S-73-47

CONDITION SURVEY, FT. DEVENS ARMY AIRFIELD, FT. DEVENS, MASSACHUSETTS.

10 R. D. Jackson, P. J. Vedros





// Jung 1973

12 18p.

Sponsored by Office, Chief of Engineers, U. S. Army

Conducted by U. S. Army Engineer Waterways Experiment Station
Soils and Pavements Laboratory
Vicksburg, Mississippi

ARMY-MRC VICKSBURG, MISS

APPROVED FOR PUBLIC RELEASE; DISTRIBUTION UNLIMITED

038 100 Gpg

#### Foreword

Authority for conducting condition surveys at selected airfields is contained in Long-Range Program, O&M,A, FY 1973, Project Q6-1: "Engineering Criteria for Design and Construction, WES," dated 1 July 1972.

The facilities at Ft. Devens Army Airfield, Ft. Devens, Massachusetts, were inspected during August 1972 by Messrs. R. D. Jackson, P. S. McCaffrey, Jr., and W. J. McKay of the Engineering Design Criteria Branch, Soils and Pavements Laboratory, U. S. Army Engineer Waterways Experiment Station (WES), Vicksburg, Mississippi. This report was prepared by Messrs. Jackson and P. J. Vedros under the general supervision of Messrs. J. P. Sale, R. G. Ahlvin, and R. L. Hutchinson of the Soils and Pavements Laboratory, WES.

COL Ernest D. Peixotto, CE, was Director of the WES during the conduct of the study and preparation of this report. Mr. F. R. Brown was Technical Director.

#### Contents

	Page
Foreword	iii
Conversion Factors, British to Metric Units of Measurement	vii
Purpose	1
Pertinent Background Data	1
General description of airfield	1
Previous reports	2
History of Airfield Pavements	2
Construction history	2
Traffic history	3
Conditions of Pavement Surfaces	14
Evaluation	4
Tables 1-4	
Photos 1-4	
Plate 1	

### Conversion Factors, British to Metric Units of Measurement

British units of measurement used in this report can be converted to metric units as follows:

Multiply	Ву	To Obtain
inches	2.54	centimeters
feet	0.3048	meters
miles (U. S. statute)	1.609344	kilometers
gallons (U. S. liquid)	3.785412	cubic decimeters
pounds (mass)	0.45359237	kilograms
rounds (force) per square inch	0.6894757	newtons per square centimeter
Fahrenheit degrees	*	Celsius or Kelvin degrees

<sup>\*</sup> To obtain Celsius (C) temperature readings from Fahrenheit (F) readings, use the following formula: C = (5/9)(F - 32). To obtain Kelvin (K) readings, use: K = (5/9)(F - 32) + 273.15.

## CONDITION SURVEY, FT. DEVENS ARMY AIRFIELD FT. DEVENS, MASSACHUSETTS

#### Purpose

1. The purpose of this report is to present the results of an inspection performed at Ft. Devens Army Airfield (DAAF), Ft. Devens, Massachusetts, during August 1972. The inspection was limited to visual observations, and no tests were conducted on the existing runways and taxiways. A layout of the airfield is shown in plate 1.

4

#### Pertinent Background Data

#### General description of airfield

- 2. DAAF is located in Middlesex County, near the town of Ayer, Massachusetts, and lies generally south of State Highway 2A and just east of the Nashua River. Ft. Devens proper is due south of the airfield. A vicinity map is shown in plate 1.
- 3. The airfield is situated generally on the floodplain of the Nashua River and is surrounded by low, rounded hills. Relief in the adjacent area is approximately 200 ft.\* The Ft. Devens area is underlain by Ayer granite, a coarse-grained, porphyritic, biotite-muscovite granite. The subgrade soils at the airfield site, in general, are of a sandy nature and vary from a brown sand (SP-SM\*\*) to a gravelly sand (SP). Groundwater exists at depths greater than 30 ft and slightly above the base level of the river. Temperature and precipitation data are presented in table 1. The amounts of departure from normal for the 1972 temperatures and precipitation were determined using periods of

\* A table of factors for converting British units of measurement to metric units is presented on page vii.

<sup>\*\*</sup> SP-SM and SP are classifications of the U. 5. Department of Defense, "Unified Soil Classification System for Roads, Airfields, Embankments, and Foundations," Military Standard MIL-STD-619B, June 1968, U. S. Government Printing Office, Washington, D. C.

record of 86 and 108 years, respectively.

4. In August 1972, the airfield consisted of a NW-SE (14-32) runway, approximately 100 ft wide and 3745 ft long; a N-S runway, 60 ft wide and 2560 ft long; two helicopter runways; four taxiways; and a parking and maintenance apron.

#### Previous reports

- 5. Previous reports pertaining to the load-carrying capabilities of the pavements at DAAF are listed below:
  - a. U. S. Army Engineer District, Boston, CE, "Pavement Evaluation Report, Ft. Devens Airfield, Massachusetts," November 1944, Boston, Massachusetts.
  - b. Ohio River Division Laboratories, CE, "Airfield Evaluation Report, Ft. Devens Army Airfield, Massachusetts," January 1968, Cincinnati, Ohio.
  - C. U. S. Army Engineer Division, New England, "Fort Devens Army Airfield, Supplemental Report of Pavement Evaluation," January 1970, Waltham, Massachusetts.

Pertinent data were extracted from these reports for use in this condition survey report.

#### History of Airfield Pavements

#### Construction history

- 6. Original construction at DAAF was completed in 1941 by the Works Progress Administration and consisted of runways that were 150 ft wide and of various lengths and a service apron with connecting taxiways. The pavement section consisted of soil cement pavement mixed in place. A tar surface seal was placed over the cured soil cement pavement. In 1942, the runways were widened to 300 ft by the Corps of Engineers with the same construction procedures as were used in the 1941 construction. Several hardstand areas were also constructed using the soil cement and tar seal. In 1944, the Navy constructed a small parking apron (400 by 75 ft) consisting of a tar surface treatment over 14 in. of gravelly sand base. The helicopter runways and parking aprons were constructed in 1958-59.
  - 7. Taxiway D was rebuilt in 1960 by U. S. Army Engineer troops.

The old bituminous surface treatments and the gravel base were scarified and compacted. A 3-1/2-in., mixed-in-place, bituminous macadam surface was then constructed. In 1961, an engine run-up apron was constructed, which was designed for a 12,000-lb, single-wheel load with 100-psi tire pressure. A summary of physical property data is presented in table 2. Traffic history

8. From 1941-1944, the airfield was used by the Army Air Corps. Traffic consisted of occasional operations of such aircraft as B-25's, B-26's, B-17's, C-47's, and A-29's. These were mostly transient aircraft operations and averaged about 5 operations per day. From April 1944 to the end of World War II, the Navy used the airfield for practice landings. Operations averaged about 350 per day with about 95 percent of this traffic involving single-engine aircraft with gross weights of 12,000 to 15,000 lb. The remaining 5 percent involved multiengine aircraft with gross weights of about 20,000 to 30,000 lb. Following Navy usage, no traffic records were kept until July 1952. From July 1952-December 1955, an average of about 180 cycles\* per month were applied. with approximately 60 percent of these operations being on the NW-SE runway. During the period January-October 1956, the average monthly cycles of traffic were approximately 360. The major portion of the above traffic involved "L" and "H" type aircraft, with only occasional traffic of the heavier "C" and "B" type aircraft. Traffic records were not available for November 1956-December 1970. Total fixed-wing traffic for 1971 amounted to 24,838 cycles. Approximately 26 percent of this traffic had gross weights of 12,500 lb or more, carried 255 gal or more of fuel, or had the capacity for at least 11 passengers. During the period 1 January-30 June 1972, traffic in the above category amounted to 5105 cycles, 3185 rotary-wing and 1920 fixed-wing cycles. C-123 traffic amounted to 916 cycles, and C-130 traffic amounted to 899 cycles. Total aircraft traffic during the above period amounted to 17,448 cycles.

<sup>\*</sup> A cycle of operation is one takeoff and one landing.

#### Conditions of Pavement Surfaces

9. In August 1972, the conditions of the pavement surfaces ranged from good to excellent. The NW-SE runway had a 1-in. leveling and a 1-in. surface course applied in 1961. In 1969, a bituminous slurry seal was applied to the surface in an effort to seal the cracks that had reflected through the 2-in. overlay from the underlying soil cement. Photo I shows both longitudinal and transverse cracks in this runway. Most of the cracks were in the transverse direction and were spaced at 25- to 50-ft intervals. None of the cracks showed evidence of movement; however, the material on each side of some of the cracks was slightly higher than the surrounding area (photo 2). This runway was considered to be in good condition (photo 3). The N-S runway is used primarily as a taxiway and was in excellent condition (photo 4). This runway was overlaid with 1 in. of bituminous concrete in 1969. The overlay for taxiway D was specified as a nominal 2 in.; however, subsequent investigation by the New England Division indicated the overlay was actually 2.5 in. thick. Taxiways B and C have been overlaid twice since they were constructed. The first overlay was 1.5 in. of bituminous concrete and the second was 2 in. Taxiway A was overlaid in 1969 with 1 in. of bituminous concrete. The taxiways were in good to excellent condition. All of the apron areas were overlaid in 1969 with 1 to 3.5 in. of bituminous concrete. The apron areas were considered to be in excellent condition.

#### Evaluation

10. A summary of the basic field evaluation is presented in table 3. Table 4 presents a summary of the pavement evaluation for overload aircraft. These evaluations were made by the New stand Division and are also contained in the report listed in subparagraph 5c. The evaluation shown in table 4 for overload aircraft is for load only and does not take into account any physical limitations such as runway length, etc.

Table 1
Temperature and Precipitation Data

Month	Average 1972 Temperature, F	Departure from Normal, F	1972 Precipitation in.	Departure from Normal, in.
January	25.8	-0.1	1.80	-2.30
February	23.0	-3.7	5.23	2.02
March	31.7	<b>-</b> 3.5	5.82	1.45
April	41.7	-5.0	3.35	-0.71
May	57.2	-1.2	5.56	1.74
June	64.9	-2.4	6.25	2.31
July	72.0	-0.3	6.15	2.69
August	68.6	-2.0	2.59	-0.66
September	62.3	-0.3	2.65	-1.46
October	47.6	-4.8	3.59	0.16
November	36.4	-4.8	7.79	3.51
December	29.1	-0.1	6.75	3.04
Annual	46.7	-2.4	57.53	11.79

Note: Lowest temperature in 1972 was 15 F on February 23; highest temperature in 1972 was 93 F on August 26.

	FACILITY				OVERLAY PAVEMENT			PAVEMENT				BASE		SUBGRADE		GENERAL
FAC OF	FORT DEVONS AAE, SOUT DEVENS, MASS. FACILITY NUMBER AND IDENTIFICATION	LENGTH	MIDTH FT	THION.	DESCRIPTION	FLEX. STR PS2	THICK.	DESCRIPTION	FLEX. STR PSI	A X		CLASSIFICATION	8 8 ×	CLASSIFICATION	8 ×	CONDITION OF AREA CONSIDERED
SIB	EX-SE runsay ends	200	100	Oj.	Ettuminous concrete		7	Accumulated seal coats		9	1308	Soil cement	8	Sand (SP)	72	
Rec	NW-SE runway interior	2745	100	2	Mituminous concrete		H	Accumulated seal costs		9	Set1	cement	90	Send (SP)	d	
RGB	Nes rupsay ends	500	09	1	Bituminous concrete		re	Accumulated seal costs		-0	5013	cement	8	Sand (SF)	×.	
Black	N-S runway interior	1560	99	1	Estuminous concrete		ri.	Accumulated seal costs		9	Sc41	Soil cement	80	Sand (SP)	d	
BSG	Helicopter runwigs No. 15-33 No. 2-20	1460 1475	07				61	Ethaninous commete		9	Sand	Sand and gravel	8	Sept (SP)	- 20	
THE	faxiway B	350	75	EV.	Bituminous concrete		0.5	Bituminds contrite		9	ffol.	Soll cement	90	3sed (3P)	76	
Tec	Taxiway C	175	25	cu	Situations concrete		0.0	Estuaincus concrete Surface trestment		9	3013	Soll sement	H <sub>o</sub>	Dand (SF)	76	
130	Taxiwny D	1050	20	2.5	Mituminosa concrete		5.0	Bituminous macadam (mixed in place)		40	Sravel	6.3	8	313ty send (37-3M)	97	
The	Taxiway A	300	100				61	Eltuminous concrete		9	Sand	Sand and gravel	05	Sand (SP)	た	
Alc	Engine run-up area	Irreg-	Irreg-	0)	Bituminous concrete		ču.	Bitumineus concrete		9	Stab	Stabilized aggregate	80	Sand (SP)	8	
AZC	Parking and maintenance sprom Irreg-	Irreg-	Irreg- ular	60 m	Bituminous concrete		50	Bitiminous concrete Surface treatment		10	Sott	Soil cement	8	Swind (SP)	2	
A3C	Farking aprons	059	100	cu.	Mituminous concrete		(r)	Hitzminous macedam (mixed in place)	80	80	Gravel	1,0	8	Silty sand (SP-SM)	n	
63	AbC Farking and access apron	Irreg-	Irreg-	et	Mitumingua concrete		2.5	Bituminous concrete		9	Grad	Graded crushed aggregate	100	Sand (SF)	2	
1 . 4	1000 muou san							Andreas and the second	-		-	-	*	The state of the s	1	-

Table 3 Summary of Basic Field Evaluation, August 1972

	Allowal Normal Period		eraft Loadings, Frost-Melti Operat	ng Period
Designation	Single-Wheel Gear	Twin-Wheel Gear	Single-Wheel Gear	
NW-SE runway	70,000	50,000+	*	*
N-S runway and taxiways B and C	55,000	50,000	*	*
Taxiway D**	34,000	47,000	30,000	37,000
Apron system	70,000+	50,000+	*	*

<sup>\*</sup> Frost evaluation is same as normal period evaluation. \*\* Basic field evaluation.

Table 4
Summary of Pavement Evaluation for Overload Aircraft

Ov	rerload Aircr	aft	Allowable	Gross Aircraft	Load, 1b
Type	Weigh		One Cycle	One Cycle	One Cycle
Aircraft	Empty	Gross	per Day	per Week	per Month
C-123	30,000	60,000	45,000		
C-131	30,700	60,000	48,000		
C-119	41,000	77,000	48,000		
C-54	39,000	82,500	48,000		
C-130	69,837	155,000	105,000	125,000	
C-124	100,000	216,000	130,000	190,000	



Photo 1. Longitudinal and transverse cracks in NW-SE runway




Photo 2. Cracks with slightly raised edges on NW-SE runway



Photo 3. General view of NW-SE runway



Photo 4. General view of N-S runway



#### LEGEND

RIB FEATURE PESIGNATION (SEE NOTE I)

#### TYPE OF FEATURE

- R-RUNWAY T-TAXIWAY A-APRON

#### TYPE TRAFFIC AREA (SEE NOTE 2)

B-B TYPE TRAFFIC

- NOTES: I FEATURE DESIGNATION DENOTES TYPE OF FEATURE, NUMBER OF FEATURE FOR GIVEN TYPE, AND TYPE OF TRAFFIC AREA.
  - 2. TRAFFIC AREA DESIGNATIONS ARE BASED ON LIGHT-LOAD CRITERIA.
  - 3. ALL PAVEMENTS ARE SURFACED WITH ASPHALTIC CO

